

Inspection Photos

7/18/2017

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 323581

Inspection Doc. Number: 682502467

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: EXTRACTION OIL & GAS INC - 10459
Location ID: 323581



Photo 1: Photo taken from the southwest end of the location, facing southeast. Photo shows stormwater erosion occurring throughout the reclamation / remediation area. 6 foot measuring stick for reference. Location appears to have had a seeding attempted, however location was not seeding along the contour of the slope. This has facilitated erosion on the location.



Photo 2: Photo taken from the southwest end of the location, facing southeast. Photo shows sediment laden stormwater runoff from the location has deposited into an irrigation ditch on the west end of the location. 6 foot measuring stick for reference.

Inspection Photos
Operator: EXTRACTION OIL & GAS INC - 10459
Location ID: 323581



Photo 3: Photo taken from the southwest end of the location, facing east. Photo shows stormwater erosion occurring throughout the reclamation / remediation area. 6 foot measuring stick for reference. Location appears to have had a seeding attempted, however location was not seeding along the contour of the slope. This has facilitated erosion on the location.



Photo 4: Photo taken from the north end of the location. Photo shows stormwater erosion occurring throughout the reclamation / remediation area. 6 foot measuring stick for reference. Location appears to have had a seeding attempted, however location was not seeding along the contour of the slope. This has facilitated erosion on the location.

Inspection Photos
Operator: EXTRACTION OIL & GAS INC - 10459
Location ID: 323581



Photo 5: Photo taken from the north end of the location. Photo shows stormwater erosion occurring throughout the reclamation / remediation area. 6 foot measuring stick for reference. Location appears to have had a seeding attempted, however location was not seeding along the contour of the slope. This has facilitated erosion on the location.



Photo 6: Photo taken from the north end of the location. Photo shows vegetative growth (likely) from a seeding. Appears location had been reseeded, however evidence of germination is scarce with the majority of the location predominantly exposed soil. Also, location was not seeding along the contour of the slope, which has facilitated erosion on the location.

Inspection Photos
Operator: EXTRACTION OIL & GAS INC - 10459
Location ID: 323581



Photo 7: Photo taken from the north end of the location. Photo shows stormwater erosion occurring throughout the reclamation / remediation area. 6 foot measuring stick for reference. Location appears to have had a seeding attempted, however location was not seeding along the contour of the slope. This has facilitated erosion on the location.



Photo 8: Photo taken from the north end of the location. Photo shows stormwater erosion occurring throughout the reclamation / remediation area. 6 foot measuring stick for reference. Location appears to have had a seeding attempted, however location was not seeding along the contour of the slope. This has facilitated erosion on the location.