

Inspection Photos
Location Name: Walker 12-2
API: 05-081-07079



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Walker 12-2
API: 05-081-07079



Photo 2. Unused 2" steel riser on left, unused 3" steel riser on right. Noxious weeds visible adjacent to 3" riser.



Photo 3. Unused 2" steel riser at wellhead.