

Inspection Photos  
Location Name: Walker 12-1  
API: 05-081-07044



**Photo 1. Overview of location taken at entrance facing northwest.**

Inspection Photos  
Location Name: Walker 12-1  
API: 05-081-07044



**Photo 2. Unused 2" steel riser on left, unused 3" steel riser on right. Noxious weeds in foreground.**



**Photo 3. Unused 2" steel riser at wellhead.**