



**Location**

Overall Good:

Emergency Contact Number:

Comment: 1-877-879-0376

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type WEEDS

Comment: Noxious weeds on location.

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date:

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Deadman # & Marked

# 4

Comment:

Corrective Action:

Date:

Type: Flow Line

#

Comment: 1 unused 2" and 1 unused 3" steel riser observed at 40.57316, -107.77594 and 1 unused 2" steel riser observed at wellhead not marked for abandonment or locked out tagged out.  
 NTO Phase 1, Part 2: Any existing flowline or pipeline riser not in use must be clearly marked using fluorescent paint, have all operating valves removed and be capped (locked out/tagged out, bull plugged, or blind flange) until it can be cut-off below grade and sealed pursuant to Rule 1103 and the statewide Flowline NTO.

Corrective Action: Comply with Phase I-Part 2 of the May 2, 2017 Flowline NTO.

Date: 05/30/2017

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 259508 Type: WELL API Number: 081-07044 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689800068	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200564">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200564</a>