

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 1: Stained soil at wellhead. One unused riser at wellhead.**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 2: Stained soil at pump jack**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 3: Stained soil at pump jack and engine**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil at tank**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 5: Unused pump removed. Two unused risers.**

Inspection Photos  
Location Name: DOC Powell #30-14-11  
API: 05-123-19447



Photo from prior inspection for comparison



Photo 6: Damaged placard on east tank, tanks are placarded

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 7: Mesh repaired**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**

**Photo 8: Stained soil around treater**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 9: Stained soil in treater house**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 10: Stained soil in treater house**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo from prior inspection for comparison**



**Photo 11: Deadman marked**

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo 12: Stained soil at engine**



**Photo 13: Unused riser at pump jack**

Inspection Photos  
Location Name: DOC Powell #30-14-11  
API: 05-123-19447



Photo 14: Unused equipment at pump jack.



Photo 15: Stained soil at treater house

**Inspection Photos**  
**Location Name: DOC Powell #30-14-11**  
**API: 05-123-19447**



**Photo 16: Stained soil at loadout valve**