

**Inspection Photos**  
**Location Name: Showers #32-5-7**  
**API: 05-123-19441**



**Photo from prior inspection for comparison**



**Photo 1: Stained soil at wellhead, no bradenhead at surface**

**Inspection Photos**  
**Location Name: Showers #32-5-7**  
**API: 05-123-19441**



**Photo from prior inspection for comparison**



**Photo 2: Stained soil at pump jack**

**Inspection Photos**  
**Location Name: Showers #32-5-7**  
**API: 05-123-19441**



**Photo from prior inspection for comparison**



**Photo 3: Deadman markings in disrepair**

**Inspection Photos**  
**Location Name: Showers #32-5-7**  
**API: 05-123-19441**



**Photo from prior inspection for comparison**



**Photo 4: Wellhead sign**