

Inspection Photos
Location Name: Hill #31-9-11
API: 05-123-19627



Photo from prior inspection for comparison



Photo 1: Stained soil at engine house

Inspection Photos
Location Name: Hill #31-9-11
API: 05-123-19627



Photo from prior inspection for comparison



Photo 2: Deadman marked



Inspection Photos
Location Name: Hill #31-9-11
API: 05-123-19627



Photo 3: Unused equipment by pump jack.



Photo 4: Stained soil at pump jack



Inspection Photos
Location Name: Hill #31-9-11
API: 05-123-19627



Photo 5: Stained soil in engine house