

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 1: Stained soil at wellhead



Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 2: Wellhead sign is for prior operator

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 3: Stained soil at crude oil loadouts. E tank (right) is actively leaking

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 4: Damaged placards on crude oil tanks

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368




Photo from prior inspection for comparison



Photo 5: W tank (left) lacking placarding, E tank (right) now placarded

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 6: Stained soil at SE corner of pumphouse

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Stained soil at SW corner of pumphouse, unused equipment

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 8: Stained soil in treater house

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 9: Gaps in netting on pit

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 10: Stained soil at NE corner remediated

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo from prior inspection for comparison



Photo 11: Stormwater erosion on N side of pit. Waddles put in place at NE corner of facility

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo 12: Unused equipment at tank battery



Photo 13: Riser at tank battery

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo 14: Stained soil at NW corner of pit



Photo 15: Detached battery sign

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo 16: Debris in treater house



Photo 17: Oil, waste in pumphouse

Inspection Photos
Location Name: Hill #31-15-8
API: 05-123-19368



Photo 18: Stained soil around produced water tank



Photo 19: Stained soil around produced water tank