

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 1: Berms repaired

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 2: Stained soil at truck loadout

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 2: Stained soil at wellhead. Bradenhead not plumbed to surface.

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 4: Stained soil at pump jack

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 5: Stained soil at engine housing

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 6: Stained soil at engine exhaust

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 7: Stained soil in treater house

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 8: Stained soil by skim

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 9: Skim covered

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 10: Stained soil in pit

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 11: Stained soil in pit

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo from prior inspection for comparison



Photo 12:

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo 13: Riser at NW corner of crude oil battery



Photo 14: Unused pipe, risers at SW corner of tank

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo 14: Stained soil at pump jack



Photo 15: Stained soil around engine in engine house

Inspection Photos
Location Name: Hill #6-1
API: 05-123-20169



Photo 16: Stained soil by vertical separator



Photo 17: Riser near separator shack