



photo 1: Facing south along the access road toward the location. Stormwater is not adequately directed toward the sediment trap shown in photo below.



photo 2: The sediment trap has filled in with sediment and needs to be maintained.



photo 3: Facing southwest toward the location.



photo 4: Facing southwest along the fill slope of the location.



photo 5: There are areas along the northeast side where erosion is occurring.



photo 6: Stormwater is flowing underneath the wattle causing erosion.



photo 7: Facing northeast along the fill slope. The vegetation has established well in this area.



photo 8: Facing southwest toward the cut slope. The vegetation has established well in this area