

Inspection Photos
Location Name: Federal Goshawk 28-13
API: 05-123-22634



Photo 1: Tanks are rusted



Photo 2: Stained soil at loadout

Inspection Photos
Location Name: Federal Goshawk 28-13
API: 05-123-22634



Photo 3: Stained soil at riser. Two risers on W side of tank battery.




Photo 4: Two risers on E side of tank battery

Inspection Photos
Location Name: Federal Goshawk 28-13
API: 05-123-22634



Photo 5: Stained soil in treater house



Photo 6: Unpermitted pit

Inspection Photos
Location Name: Federal Goshawk 28-13
API: 05-123-22634



Photo 7: Holes in netting



Photo 8: Unmarked deadman

Inspection Photos
Location Name: Federal Goshawk 28-13
API: 05-123-22634



Photo 9: Stained soil at wellhead. No bradenhead at surface.



Photo 10: Stained soil in engine house.