



*Figure 1 - Rocky Mountain II 1 wellhead sign, wellhead, and flowline riser. Note: flowline riser is neither capped, painted, nor tagged (as required by 2017 Flowline NTO). Both wellhead and flowline are open to atmosphere and wellhead is sitting in a depression.*





*Figure 2 - Junk and debris located SW of wellhead (abandoned prime mover shed, day tank, propane tank, pipe, assorted junk).*





Figure 3 - Tank battery (top) with unused, overturned tank outside of berm (bottom).



*Figure 4 - Localized, oil-stained soil at south tank.*





*Figure 5 - Uncapped, unmarked flowline riser at SW corner of separator.*



*Figure 6 - Assorted photos of unused equipment, junk, debris, stained soil, and weeds west of tank battery and separator.*