

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 1. Widened area/filled in drainage/spoil dump along access road



Photo 2. Industrial materials mixed in with spoil piles

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 3.



Photo 4. Spoil piles eroding into drainage, no stormwater/sediment controls

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 5. Widened area where drainage has been filled in by dumping spoil and waste materials from unknown origin



Photo 6. Heavy equipment staged by spoil piles, note recent tire tracks

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 7. Pored concrete and rebar blocks on edge of staging area

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 7. 2013 aerial of project area and existing road prior to CX-2 construction

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 8. 2015 aerial after construction, note built out spoil dump in drainage at prominent bend in access road

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360

CX-2 (2015 aerial) access close-up



Photo 9. close-up of spoil dump in drainage, note heavy equipment staged at time of photo

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 10. Newly disturbed area NW corner of location, well sign, slash pile. Note perimeter wattles have not been re-installed



Photo 11. Newly disturbed area, seeding/stabilization not yet performed

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 12 Flowering weed on SW corner of fill slope



Photo 13. Straw wattle covered in material and in disrepair NW corner

Inspection Photos
Location Name: Kinder Morgan CX-2
API: 05-083-06720
Inspection Number: 685200360



Photo 9. De minimis cement on east side of graveled pad