

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/19/2017

Submitted Date:

07/21/2017

Document Number:

674901800

### FIELD INSPECTION FORM

Loc ID 325156 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Fischer, Reed	720-484-2346	Inspections@catamountep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115752	PIT				-	FORD OLSON UNIT 1	EI
214148	WELL	PR	05/19/2003	GW	067-05464	FORD-OLSON UNIT 1	EI

**General Comment:**

On 7/19/17 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Ford Olson #1. For the most recent field inspection report of this facility, please refer to document #674901465. After desktop review and location inspection, pit #115752 has been closed in the COGIS database.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Open topped produced water vessel has label and placard.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	SW marker not found.		
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.115070,-107.718273
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Inadequate
-----------	------------

Other (Content)	
Other (Capacity) 20 bbl.	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 115752 Type: PIT API Number: - Status:        Insp. Status: EI

Facility ID: 214148 Type: WELL API Number: 067-05464 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Compaction	Pass			
Waddles	Fail					
Sediment Traps	Pass	Gravel	Pass			
Rip Rap	Pass	Ditches	Pass			

Comment: [Wattles are undercut.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On 7/19/17 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Ford Olson #1. For the most recent field inspection report of this facility, please refer to document #674901465.                      After desktop review and location inspection, pit #115752 has been closed in the COGIS database.                      Storm water erosion controls need maintenance.</p>	hughesj	07/21/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901801	Undercut wattle	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203497">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203497</a>
674901802	Location erosion.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203498</a>