

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/19/2017

Submitted Date:

07/21/2017

Document Number:

674901803**FIELD INSPECTION FORM**
 Loc ID 311927 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278443	WELL	PR	10/02/2014	GW	067-09058	FC SOUTHERN UTE COM 006 2	EI

General Comment:

On July 19, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP FC Southern Ute Com 006 #2. For the most recent field inspection report for this facility, please refer to document #674901618.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance. Old sign has been removed.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around well head and pumping unit.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Stock panel fencing around separator, meter run, and PBV.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	SW anchor not marked.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Natural gas powered.		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.116026,-107.780669	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	278443	Type:	WELL	API Number:	067-09058	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	295729	1733166	
	295729	1733166	

COGCC Comments

Comment	User	Date
On July 19, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the BP FC Southern Ute Com 006 #2. For the most recent field inspection report for this facility, please refer to document #674901618. Corrective actions noted in that document have been performed.	hughesj	07/21/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901804	Stained soil around well head has been removed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203522
674901805	Secondary containment for lube oil container.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203523