

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/16/2017

Submitted Date:

07/17/2017

Document Number:

673715749

FIELD INSPECTION FORM

Loc ID 449153 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61650
Name of Operator: MURFIN DRILLING COMPANY INC
Address: 250 N WATER ST STE 300
City: WICHITA State: KS Zip: 67202

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Gunzelman, Shauna	316-267-3241	sgunzelman@murfininc.com	Designated Agent
Melland, Tom	316-858-8695	tmelland@murfininc.com	Production Engineer
Kerstetter, Sarah	316-858-8668	skerstetter@murfininc.com	Designated Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449154	WELL	DG	07/11/2017		073-06718	Milk Money #3	DG

General Comment:

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 449154 Type: WELL API Number: 073-06718 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Mufin Rig 25 Pusher/Rig Manager: Ray
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids

Management:

Lined Pit: YES Unlined Pit: YES Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: NO Disposal Location: _____

Comment: Spudded surface on 7/15/2017, Inspector was contacted prior to spud. Surface drilled to 460', 8 5/8" pipe set.

Corrective Action: _____ Date: _____

Cement

Cement Contractor

Contractor Name: QES Contractor Phone: 785-672-8822

Surface Casing

Cement Volume (sx): 300 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: Class A cement

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening	Pass					
Ditches	Pass	Tracking Pad	Pass	Spill Response	Pass	
Berms	Pass	Berms	Pass	Covering Materials	Pass	
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Liners under mud tanks and around wellhead.
Other	Pass					vegetation

Comment: Top soil piles separated and stored on east, west and north sides of location. All piles/berms are compacted.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Water Fresh Lined: YES Pit ID: _____ Lat: 39.156290 Long: -103.687720

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: HDPE Liner Condition: Adequate

Comment:

Corrective Action Date: g

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action Date: _____

Type: Reserve Lined: NO Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: g

Fencing:			
Fencing Type:	Fencing Condition:		
Comment:	<input style="width: 100%;" type="text"/>		Date:
Corrective Action	<input style="width: 100%;" type="text"/>		
Netting:			
Netting Type:	Netting Condition:		
Comment:	Trench location directly south of fresh water pit		Date:
Corrective Action	<input style="width: 100%;" type="text"/>		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:	
Comment:	<input style="width: 100%;" type="text"/>		Date:
Corrective Action	<input style="width: 100%;" type="text"/>		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401343219	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4198758
673715755	Murfini Milk MOney #3 Surface Cementing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4198757