

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2017

Submitted Date:

07/17/2017

Document Number:

680102015

### FIELD INSPECTION FORM

Loc ID 316749 Inspector Name: Colby, Lou On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10055  
 Name of Operator: SAGOUSPE\* JEAN P  
 Address: P O BOX 1365  
 City: LOS BANOS State: CA Zip: 93635

**Findings:**

- 5 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Waldron, Emily		emily.waldron@state.co.us	Field Inspector
Burger, Craig		craig.burger@state.co.us	NW Region Engineer
Colby, Lou		lou.colby@state.co.us	NW Reclamation Inspector

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232627	WELL	DM	05/03/1975	GW	107-06041	BEAR VICTOR 16-11	RI

**General Comment:**

Inspector was in area for 2017 Flowline NTO Inspection 1000' Buffer of adjacent Location PA Well. Subject Well appeared closer to Residence than NTO List Well. During Reclamation Inspection of Bear-Victor Well API#107-06041 Audible leak (Hissing) sound was noted from Well head. Operator was called/notified & this Inspection has Area Field Inspector & Engineer as contacts. Refer to Facilities Section for comments & Corrective Actions. Well appears to be a Domestic TA Well. Reclamation focused Inspection of Location will be submitted separately. Photo log is attached.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

**Inspected Facilities**

Facility ID: 232627 Type: WELL API Number: 107-06041 Status: DM Insp. Status: RI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Audible leak was detected at Wellhead. Operator has been notified by Phone Call (Voice Mail message left). There is no email Contact in Files for Operator, Inspection will be Mailed US Post if email contact not Found by Phone inquiry.

**Corrective Action:** Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/19/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401343800	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4199175">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4199175</a>
680102016	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4199164">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4199164</a>