



**photo 1:** Facing northeast along the main access road. Lat/Long:37.091603,-104.942226



**photo 2:** Facing northeast along the main access road. Stormwater is not being properly diverted which is causing erosion along the road.



**photo 3:** Facing back along the main road. The ditches along the side of the road have filled in with sediment and stormwater is not properly diverted to the culverts.



**photo 4:** Facing south at the location.



**photo 5:** There is oil on the engine skid.



**photo 6:** There is 2 ft freeboard in the pit as shown by the marker.