

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2017

Submitted Date:

07/18/2017

Document Number:

689500014**FIELD INSPECTION FORM**

Loc ID 314491 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone        | Email            | Comment |
|-----------------|--------------|------------------|---------|
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 228832      | WELL | PR     | 07/01/2000  | OW         | 103-05819 | A. C. MCLAUGHLIN 29 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                  |       |  |
|----------------------|------------------|-------|--|
| <b>Signs/Marker:</b> |                  |       |  |
| Type                 | WELLHEAD         |       |  |
| Comment:             | Present/complete |       |  |
| Corrective Action:   |                  | Date: |  |
| Type                 | CONTAINERS       |       |  |
| Comment:             | Present/complete |       |  |
| Corrective Action:   |                  | Date: |  |

Emergency Contact Number:

Comment: 970-675-3700

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                           |                                      |       |                 |
|---------------------------|--------------------------------------|-------|-----------------|
| <b>Equipment:</b>         |                                      |       | corrective date |
| Type: Ancillary equipment | # 1                                  |       |                 |
| Comment:                  | Chem tote with secondary containment |       |                 |
| Corrective Action:        |                                      | Date: |                 |
| Type: Submersible Pump    | # 1                                  |       |                 |
| Comment:                  |                                      |       |                 |
| Corrective Action:        |                                      | Date: |                 |
| Type: Deadman # & Marked  | # 4                                  |       |                 |
| Comment:                  |                                      |       |                 |
| Corrective Action:        |                                      | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |  |                       |            |
|----------------------|--|-----------------------|------------|
| Facility ID: 228832  | Type: WELL   | API Number: 103-05819 | Status: PR |
| Insp. Status: PR     |  |                       |            |
| Producing Well       |  |                       |            |
| Comment:             | PR - via sumbersible pump, no leaks/venting. Remote pressure monitoring present. |                       |            |
| Corrective Action:   |  | Date:                 |            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |

Comment: No sediment flow evidentCorrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401346168    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200790">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200790</a> |