

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2017

Submitted Date:

07/18/2017

Document Number:

689800065**FIELD INSPECTION FORM**
 Loc ID 313146 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10396Name of Operator: SWN PRODUCTION COMPANY LLCAddress: PO BOX 12359City: SPRING State: TX Zip: 77391**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Maneotis, Karen	970-620-6099	Karen_Maneotis@swn.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262674	WELL	TA	08/05/2013	GW	081-07079	WALKER 12-2	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-877-879-0376

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Noxious weeds on location.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	07/28/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	1 unused 2" steel riser and 1 unused 3" steel riser observed at 40.57413, -107.77858 and 1 unused 2" steel riser observed at wellhead not marked for abandonment or locked out tagged out. NTO Phase 1, Part 2: Any existing flowline or pipeline riser not in use must be clearly marked using fluorescent paint, have all operating valves removed and be capped (locked out/tagged out, bull plugged, or blind flange) until it can be cut-off below grade and sealed pursuant to Rule 1103 and the statewide Flowline NTO.		
Corrective Action:	Comply with Phase I-Part 2 of the May 2, 2017 Flowline NTO.		Date: 05/30/2017
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 262674 Type: WELL API Number: 081-07079 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401345816	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200581</a>
689800066	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200563">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4200563</a>