



**Photo 1: View of the project area from the southwestern corner facing center.**



**Photo 2: View of the southern portion of the project area from the southwestern corner facing eastward. Black netting debris needs to be properly installed or removed.**



**Photo 3: View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing, largely with grasses such as western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).**



**Photo 4: View of musk thistle that was recently treated.**



**Photo 5: View of black netting in the northern portion of the project area. This needs to be removed.**