

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 1: Access road dropping into canyon. Rock, gravel, and dirt with drainage ditch between base of hill and road.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 2: Access road is 12' – 13' wide from ditch edge to the vegetation along outside edge of road.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 3: Tight spot on access road. Not as steep of grade but still driving towards bottom of slope. This section of road narrows to 9' – 10' from ditch edge to tree limbs growing over road.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 4: Tight spot as road bends to the slightly to the left close to the bottom. Road is 11' – 12' wide from ditch edge to tree limbs growing over road.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 5: Access road drainage crossing. The sidewall has collapsed at culvert on down slope side of the road.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 6: Access road is 19' wide from edge to edge across top of culvert.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 7: View looking down into drainage on the down slope side of road.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 8: Just past the culvert on the drainage crossing the road narrows to 13' between edge of drainage to above ground steel flow line. This would be an area of concern as evidenced by possible weakened walls of drainage.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 9: View of flowline at right edge of photo where to road narrows to 13'.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 10: Wider view of above ground flowline along access road that creates tight spot where flowline crosses drainage.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 11: Access road tight spot where erosion has washed channel out on drainage edge of road. Road is 11' from above ground flowline to edge of erosion.

- Access road condition survey for the Sanchez 4 05-067-05321 and Sanchez 2 05-067-05345.



Photo 12: Measured from edge of erosion to steel flowline.