

Location

Lease Road:			
Type	Main		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	OK		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	CABLE HAR5NESS AND PIECE OF BELT NEED REMOVED THIS IS THE THIRD INSPECTION I WILL TURN THIS IN AS A NOAV IF THIS DOES NOT GET TAKEN CARE OF		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: <u>08/20/2017</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	INTERMITTER CONTROLLER ON WELLHEAD		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 240699 Type: WELL API Number: 123-08487 Status: SI Insp. Status: SI

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

BradenHead

Comment: [Bradenhead plumbed to surface](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
DOCUMENT # 685502493, DATED 4/19/17, NOTHING HAS BEEN DONE TO THIS LOCATION	montoyaj	07/20/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401349281	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4202815
685503365	WELLHEAD AND TRASH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4202795