

**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo from prior inspection for comparison**



**Photo 1: Stained soil at wellhead**

**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo from prior inspection for comparison**



**Photo 2: Staining at flare**



**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo from prior inspection for comparison**



**Photo 3: Weeds at tank battery, unused ECD. Flare.**

**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil at loadout**

**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo from prior inspection for comparison**



**Photo 5: No capacities on production tanks. No safety placarding on produced water tank.**



**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo 6: Unused riser at flare.**



**Photo 7: Debris at E side of facility.**

**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo 8: Unused risers at separator**



**Photo 9: Unused riser at wellhead**



**Inspection Photos**  
**Location Name: Legget 1-5H**  
**API: 05-123-35277**



**Photo 10: Unused equipment at pump jack**



**Photo 11: Stained soil at engine**