

Inspection Photos  
Location Name: Reinholt 12-6  
API: 05-001-08163



**Wellhead** Corrective action: Emergency Contact Info



**Supply scrubber, note: unidentified 1" poly riser**  
**39.983924, -104.947282**

**Inspection Photos**  
**Location Name: Reinholt 12-6**  
**API: 05-001-08163**



**Long run oil drum Note: fluid spilled on concrete pumping unit base.**



**Treater's**

Inspection Photos  
Location Name: Reinholt 12-6  
API: 05-001-08163



**Battery Signage** Corrective action: Emergency contact info missing



**Battery Frontage**

Inspection Photos  
Location Name: Reinholt 12-6  
API: 05-001-08163



Location view **Corrective action: Weeds, storage of unused equipment (tubing)**

Separator housing

Inspection Photos  
Location Name: Reinholt 12-6  
API: 05-001-08163



Inside separator housing **Note: unidentified risers (5)**  
**39.979830, -104.944194**



Inside separator housing **Corrective action: Storage of equipment**

**Inspection Photos**  
**Location Name: Reinholt 12-6**  
**API: 05-001-08163**



**Meter runs**



**Unidentified risers both 2" steel, and 1" poly.**  
**39.983979, -104.946858**

**Inspection Photos**  
**Location Name: Reinholt 12-6**  
**API: 05-001-08163**



**Water tank** Corrective action: Weeds, and berm maintenance.



**Location** Corrective actions: storage of unused equipment ( Fiberglass tank) trash, weeds.