

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/26/2017

Submitted Date:

07/27/2017

Document Number:

687400118**FIELD INSPECTION FORM**
 Loc ID 335733 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: 1252 CAMERON RDCity: SEQUIM State: WA Zip: 98382**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**19 Number of Comments9 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
CONN, LIONEL	403-870-5141	lconn@live.ca	inspections
Leonard, Mike		mike.leonard@state.co.us	
Ellsworth, Stuart		stuart.ellsworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202758	WELL	PR	07/31/2008	OW	001-08163	REINHOLT 12-6	PR

General Comment:[Well located within 1000' NTO buffer.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	No emergency contact info at battery, see photos		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/27/2017
Type	WELLHEAD		
Comment:	No emergency contact info at wellhead, see photos		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/27/2017

Emergency Contact Number:			
Comment:	No emergency contact info present on any signage		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/27/2017

Good Housekeeping:			
Type	WEEDS		
Comment:	Battery location has severe weed overgrowth, around production tanks, water tank, and related berms. See Photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/06/2017
Type	UNUSED EQUIPMENT		
Comment:	Unused fiberglass storage tank on location, see photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	
Type	STORAGE OF SUPL		
Comment:	Large amounts of unused equipment being stored inside of separator housing (parts and supplies), several joints of 2"x30' tubing stored on racks next to outdoor separator. See Photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/27/2017
Type	TRASH		
Comment:	Location is littered in multiple areas, see photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/27/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: Long run drum has drained onto concrete pumping unit base, no fluid on soil. See photos

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Location has shared electronic access gate with neighboring outdoor storage and excavation business.		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment:	4 strand barbed wire			
Corrective Action:			Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	240V electric pump tied into flowlines from treaters to tanks.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Scrubber vessel located inside of separator housing unit.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 2		
Comment:	Both located inside of housing unit		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:	One separator located inside housing unit, one outside.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Propane tank outside of housing unit.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Dense weeds growing on berms, see photos.			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			
			Date:	08/06/2017

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 202758 Type: WELL API Number: 001-08163 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: Prodction has not been reported since December 2016.Corrective Action: Report production via Form 7 as required by Rule 206Date: 08/06/2017**COGCC Comments**

Comment	User	Date
<p>Separator housing unit has 9 unidentified risers inside of it. Directly east of the wellhead, there is an additional 3 more unidentified risers, see attachment for photos with GPS coordinates.</p> <p>Well and related production facility dont appear to have been operated in some time, upon speaking with surface owner it was communicated someone was operating the wells and attempting to clean up the facilities at the beginning of the year, but they have since abandon efforts.</p> <p>No risers have been identified as per the May 2017 NTO as of 7/27/2017.</p> <p>Well flows to commingled battery with Brink S-2 (001-09363) Croff 12-5 (001-08162), Lenart S-1 (001-09362), and Elms 12-4 (001-08153). Surface equipment and any of any respective corrective actions will be listed on this inspection form.</p> <p>Please see detailed attached PDF for photos and descriptions.</p>	kraicha	07/27/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400119	PDF inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4209864