

**Inspection Photos**  
**Location Name: Marie Gerhardt B 5**  
**API: 05-123-08916**



**Photo from prior inspection for comparison**



**Photo 1: Stained soil removed**

**Inspection Photos**  
**Location Name: Marie Gerhardt B 5**  
**API: 05-123-08916**



**Photo from prior inspection for comparison**



**Photo 2: Pump jack in use**



**Inspection Photos**  
**Location Name: Marie Gerhardt B 5**  
**API: 05-123-08916**



**Inactive riser at NE corner of pump jack**