

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2017

Submitted Date:

07/21/2017

Document Number:

674901794**FIELD INSPECTION FORM**

Loc ID 393155	Inspector Name: Hughes, Jim	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 13 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>77035</u> Name of Operator: <u>SCOW* MAYLON</u> Address: <u>P O BOX 1735</u> City: <u>HONOLULU</u> State: <u>HI</u> Zip: <u>96806-</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224353	WELL	DA	10/10/1984	DA	083-06418	PILCHER 1	EI

General Comment:

On July 13, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maylon Scow Pilcher #1. The purpose of this site visit was to evaluate the location at the request of the COGCC ODO Program Staff. For the most recent field inspection report of this facility, please refer to document #680600671.

Location

Lease Road:			
Type	Access		
comment:	Two track dirt road.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	No PA marker observed.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted or information inaccurate on tanks or containers		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/21/2017

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Leaking AST on location.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	10/23/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	Tank	<= 1 bbl	
Comment:	AST is leaking fluids.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 07/21/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		37.336060,-108.283490
Comment: AST is leaking near base.					
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment berm.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 08/21/2017

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**Type of Spill: OIL

Estimated Spill Volume: _____

Comment: AST is leaking fluids.Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.Date: 07/21/2017Reportable: NOGPS: Lat 37.336060Long -108.283490

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

SampleSample Type: SOIL GRABTime: 07/13/17 13:30 (MM/dd/yyyy hh:mm)GPS: Lat 37.336550Long -108.283290

BTEX: _____ TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____

Dissolved Methane: _____ Composition: _____ Stable Isotopes: _____ 8260: _____

8270: _____ RCRA Metals: _____ 910-Metals: _____ PAH: _____

Other: Table 910-1 constituents.Comment: Background sample.**Sample**Sample Type: SOIL GRABTime: 07/13/17 12:20 (MM/dd/yyyy hh:mm)GPS: Lat 37.336060Long -108.283490

BTEX: _____ TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____

Dissolved Methane: _____ Composition: _____ Stable Isotopes: _____ 8260: _____

8270: _____ RCRA Metals: _____ 910-Metals: _____ PAH: _____

Other: Table 910-1 constituents.Comment: Sample of stained material next to AST.**Sample**Sample Type: SOIL GRABTime: 07/13/17 12:45 (MM/dd/yyyy hh:mm)GPS: Lat 37.336510Long -108.283550

BTEX: _____ TPH: _____ Anion: _____ Captions: _____ General Chemistry: _____

Dissolved Methane: _____ Composition: _____ Stable Isotopes: _____ 8260: _____

8270: _____ RCRA Metals: _____ 910-Metals: _____ PAH: _____

Other: Table 910-1 constituents.Comment: Sample collected from inside depression.**Lab:**

Lab Name _____

ESC _____

COGCC Comments

Comment	User	Date
<p>On July 13, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maylon Scow Pilcher #1. The purpose of this site visit was to evaluate the location at the request of the COGCC ODO Program Staff. For the most recent field inspection report of this facility, please refer to document #680600671.</p> <p>During this field inspection leaks were observed in an unused AST. This tank does not have any labels or placards. The tank has several weep holes near the base. The tank does not seem to contain much fluid. Stained soil at the base of the tank was sampled for Table 910-1 contaminants of concern.</p> <p>A depression approximately 50 yards north of the AST was the location of sample ID #0713171245.</p> <p>A background sample was collected from 37.33655, -108.28329.</p>	hughesj	07/21/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401350119	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203410
674901795	Leaking AST.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203405
674901796	Sample ID #0713171220 location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203406
674901797	Sample ID #0713171245 location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203407
674901798	Sample ID #0713171310 location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203408
674901799	View of access to location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203409