

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/19/2017

Submitted Date:

07/21/2017

Document Number:

674901800**FIELD INSPECTION FORM**

Loc ID 325156 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115752	PIT				-	FORD OLSON UNIT 1	EI
214148	WELL	PR	05/19/2003	GW	067-05464	FORD-OLSON UNIT 1	EI

General Comment:

On 7/19/17 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Ford Olson #1. For the most recent field inspection report of this facility, please refer to document #674901465. After desktop review and location inspection, pit #115752 has been closed in the COGIS database.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Open topped produced water vessel has label and placard.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	SW marker not found.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top		37.115070,-107.718273
Comment:					
Corrective Action:		Date:			

Paint

Condition: Inadequate

Other (Content)	
Other (Capacity) 20 bbl.	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>115752</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status:	<u></u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>214148</u>	Type:	<u>WELL</u>	API Number:	<u>067-05464</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Ditches	Pass			
Ditches	Pass	Compaction	Pass			
Sediment Traps	Pass	Gravel	Pass			
Waddles	Fail					

Comment: Wattles are undercut.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On 7/19/17 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Ford Olson #1. For the most recent field inspection report of this facility, please refer to document #674901465. After desktop review and location inspection, pit #115752 has been closed in the COGIS database. Storm water erosion controls need maintenance.	hughesj	07/21/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401350223	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203500
674901801	Undercut wattle	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203497
674901802	Location erosion.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203498