

Inspection Photos

7/28/2017

Operator: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709

Doc. #: 675103751

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Operator: OILFIELD SALVAGE & SERVICE CO - 65550

Location: 311709



Photo 1: Photo taken from the location. Photo shows large hole on the location. Previous corrective actions required operator to repair hole. No work appears to have been conducted. 6 foot measuring stick for reference.



Photo 2: Photo taken from the south end of the location, facing south. Photo shows large un-vegetated area experiencing erosion. Photo shows stormwater and sediment control BMPs have not been installed per CAs from inspection doc. # 682501478 and doc # 682501125. Areas have continued to degrade due to erosion. 6 foot measuring stick for reference.



Photo 3: Photo taken from the south end of the un-vegetated area, facing north. Photo shows large un-vegetated area experiencing erosion. Photo shows stormwater and sediment control BMPs have not been installed per CAs from inspection doc. # 682501478 and doc # 682501125. Areas have continued to degrade due to erosion. 6 foot measuring stick for reference.



Photo 4: Photo taken from the southwest end of the un-vegetated area, facing north. Photo shows large un-vegetated area experiencing erosion. Photo shows stormwater and sediment control BMPs have not been installed per CAs from inspection doc. # 682501478 and doc # 682501125. Areas have continued to degrade due to erosion. 6 foot measuring stick for reference.



Photo 5: Photo taken from the southwest end of the unvegetated area, facing north. Photo shows large un-vegetated area experiencing erosion. Photo shows stormwater and sediment control BMPs have not been installed per CAs from inspection doc. # 682501478 and doc # 682501125. Areas have continued to degrade due to erosion. 6 foot measuring stick for reference.



Photo 6: Photo taken from the southeast end of the unvegetated area, facing north. Photo shows large un-vegetated area experiencing erosion. Photo shows stormwater and sediment control BMPs have not been installed per CAs from inspection doc. # 682501478 and doc # 682501125. Areas have continued to degrade due to erosion. 6 foot measuring stick for reference.

Operator: OILFIELD SALVAGE & SERVICE CO - 65550

Location: 311709



Photo 7: Photo taken from the well location. Photo shows vegetation has not achieved uniform desirable perennial vegetative cover to that of the reference. Photo also shows no additional reclamation activities have taken place per previous CAs