

Inspection Photos
Well API 123-14055



Photo 1: Photo taken from the Robb-PM #15-7 well location, facing west. Photo shows riser remaining at well location. Records indicate Bayswater as the last operator on record, however an extraction sticker has been placed on the sign.



Photo 2: Photo taken from the Extraction battery location. Photo shows equipment associated with the Robb-PM F #15-7 appears to have been disconnected, but has not been removed per 1004.a.

Inspection Photos
Well API 123-14055



Photo 3: Photo taken from the Extraction battery location. Photo shows equipment associated with the Robb-PM F #15-7 appears to have been disconnected, but has not been removed per 1004.a.



Photo 4: Photo taken from the Extraction battery location. Photo shows equipment associated with the Robb-PM F #15-7 appears to have been disconnected, but has not been removed per 1004.a. Photo also show risers that have not been marked or removed per phase I and II of the May 2, 2017 Flowline or Pipeline NTO, and per rule 1004.a.