

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2017

Submitted Date:

07/28/2017

Document Number:

680601821**FIELD INSPECTION FORM**
 Loc ID 316837 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10453Name of Operator: CCI PARADOX UPSTREAM LLCAddress: 600 TRAVIS STREET SUITE 300City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|---------------------------|---------------------------------|
| Nowak, Scott | | scottn@bogresources.com | All Inspections |
| Schaffner, Chrissy | | chrissy.schaffner@cci.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 269044 | WELL | TA | 01/01/2017 | GW | 113-06126 | ANDY'S MESA FEDERAL 37 | RI |

General Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

| Inspected Facilities | | | | |
|----------------------|------------|-----------------------|------------|------------------|
| Facility ID: 269044 | Type: WELL | API Number: 113-06126 | Status: TA | Insp. Status: RI |
| | | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Revegetation is progressing within the interim reclamation areas and is reflective of reference area vegetation. A vegetation assessment was conducted and the results are provided in the photos of this inspection.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

| | |
|--|--|
| Date Final Reclamation Started: _____ | Date Final Reclamation Completed: _____ |
| Final Land Use: _____ | |
| Reminder: _____ | |
| Comment: <div style="border: 1px solid black; height: 30px; width: 100%;"></div> | |
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ |
| Debris removed _____ | No disturbance /Location never built _____ |
| Access Roads _____ | Regraded _____ |
| Contoured _____ | Culverts removed _____ |
| Gravel removed _____ | |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
| Compaction alleviation _____ | Dust and erosion control _____ |
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ |
| Weeds present _____ | Subsidence _____ |
| 1004.d. FINAL VEGETATION TRANSECT | |
| TRANSECT RESULTS OF DISTURBED AREA% _____ | |
| TRANSECT RESULTS OF REFERENCE AREA% _____ | |
| TOTAL % OF DESIRABLE VEGETATION COVER _____ | |
| VEGETATIVE COVER _____ | |
| Comment: <div style="border: 1px solid black; height: 30px; width: 100%;"></div> | |
| Corrective Action: <div style="border: 1px solid black; height: 30px; width: 100%;"></div> | |
| Overall Final Reclamation _____ | Well Release on Active Location <input type="checkbox"/> |
| Multi-Well Location <input type="checkbox"/> | |

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|---|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |
| <p>Comment: Stormwater erosion largely appears to be controlled on the location at this time. However, wattles are full of sediment and need replacement, and rilling is occurring along the southern edge of the working area.</p> <p>Corrective Action: <input type="text"/></p> <p>Date: _____</p> <p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p> | | | | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 680601822 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4210092 |