

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo from prior inspection for comparison



Photo 1: Stained soil at wellhead

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo from prior inspection for comparison



Photo 2: Stained soil at riser removed.

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo from prior inspection for comparison



Photo 3: Stained soil removed

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo from prior inspection for comparison



Photo 4: Weeds controlled

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo 5: Risers at manifold



Photo 6: Riser, debris at manifold.