

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401353184  
Date Received:  
07/25/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Jeff Rickard	720 737-5144	jrickard@extractionog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682502499  
Inspection Date: 07/19/2017 FIR Submit Date: 07/20/2017 FIR Status:

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC Company Number: 10459  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 323643

Location Name: BRANTNER-65N65W Number: 30NESE County:  
Qtrqr: NESE Sec: 30 Twp: 5N Range: 65W Meridian: 6  
Latitude: 40.366150 Longitude: -104.699850

FACILITY - API Number: 05-123-00 Facility ID: 323643

Facility Name: BRANTNER-65N65W Number: 30NESE  
Qtrqr: NESE Sec: 30 Twp: 5N Range: 65W Meridian: 6  
Latitude: 40.366150 Longitude: -104.699850

CORRECTIVE ACTIONS:

1 ☒ CA# 86947

Corrective Action: Abide by Phase I and Phase II of the May 2, 2017 Flowline NTO for removal of all abandoned Risers/ Flowlines/ Pipelines. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all Risers/ Flowlines/ Pipelines

Date: 08/20/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: The riser noted in the inspection is a gathering line riser and not a flowline riser, and is therefore not subject to the NTO. Extraction has put in a request to the midstream operator to remove the riser.

COGCC Decision: Approved

COGCC Representative: See supervisor comments

COGCC Supervisor: After internal discussions, it is acknowledged that the riser identified in the inspection as a gathering line. However, the gathering line is abandoned and per 1004.a reclamation requirements must be removed. The inspection will be modified to remove the CA in the pipeline section to account for the riser being a gathering line riser. Additionally, a CA will be added to the final reclamation section of the inspection to remove that same riser as a gathering line per 1004 a . COGCC appreciates that Extraction is now working with the gathering company to remove the riser.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Rickard

Signed: \_\_\_\_\_

Title: REgulatory Compliance Co

Date: 7/25/2017 1:39:47 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

401353184	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files