

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2017

Submitted Date:

07/25/2017

Document Number:

687900179**FIELD INSPECTION FORM**Loc ID 420752 Inspector Name: DURAN, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Operator Information:**OGCC Operator Number: 10471Name of Operator: ARP PRODUCTION COMPANY LLCAddress: 101 MCQUISTON DRIVECity: JACKSON CENTER State: PA Zip: 16133**Contact Information:**

| Contact Name       | Phone                     | Email                      | Comment                   |
|--------------------|---------------------------|----------------------------|---------------------------|
| Mattorano, Michael | 575-445-6704/505-652-0416 | mmattorano@atlasenergy.com | Production superintendent |
| Koehler, Bob       |                           | bob.koehler@state.co.us    |                           |
| Berry, Matthew     | 575-445-6785/505-652-8275 | mberry@atlasenergy.com     | Production Foreman        |
| Madison, Randy     | 575-445-6706/575-420-1120 | rmadison@atlasenergy.com   | EHS Specialist            |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 420756      | WELL | IJ     | 05/01/2014  | DSPW       | 071-09838 | VPR C 204 WDW | AC          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                |                        |       | corrective date |
|---------------------|------------------------|-------|-----------------|
| Ancillary equipment | # 1                    |       |                 |
| Comment:            | Wellhead and plumbing. |       |                 |
| Corrective Action:  |                        | Date: |                 |
| Deadman # & Marked  | # 3                    |       |                 |
| Comment:            |                        |       |                 |
| Corrective Action:  |                        | Date: |                 |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 420756 Type: WELL API Number: 071-09838 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: 1170

UIC Routine

Inj./Tube: Pressure or inches of Hg -21" Hg Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: DKENG

TC: Pressure or inches of Hg 4 psig Previous Test Pressure \_\_\_\_\_ Last MIT: 06/14/2016

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Brhd : Not possible. PUMP FEED and sometimes GRAVITY FEED. Tanks about 6 miles away near the VPR C 39 WDW.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment                                   | User   | Date       |
|---|--------|------------|
| <a href="#">Next MiT on (06/15/2021).</a> | duranj | 07/25/2017 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401353738    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207351">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207351</a> |