

Inspection Photos
Location ID: 418750



1) Tubing on ground north side of location



2) Battery looking south

Inspection Photos
Location ID: 418750



3) Weeds on east side of tank battery



4) Weeds on east side of tank battery

Inspection Photos
Location ID: 418750



5) Weeds on north side of battery



6) Scrubber drain on north ECD plumbed through fence

Inspection Photos
Location ID: 418750



7) Scrubber drain plumbed outside of fence on east side of battery-note distressed vegetation



8) Distressed vegetation from ECD scrubber drain

Inspection Photos
Location ID: 418750



9) Unmarked/unused 1" steel riser at south ECD



10) Weeds inside of tank battery looking west, no water tank signage

Inspection Photos
Location ID: 418750



11) Weeds inside of tank battery



12) Weeds inside tank battery on south side

Inspection Photos
Location ID: 418750



13) Weeds south of tanks



14) Weeds on west side of tanks looking north

Inspection Photos
Location ID: 418750



15) Unmarked/unused 1" steel riser next to northeast tank



16) Unmarked/unused 1" steel riser next to northwest tank

Inspection Photos
Location ID: 418750



17) Weeds inside of berm, no signage on water tank labeling contents, capacity, NFPA label



18) No signage on water tank

Inspection Photos
Location ID: 418750



19) Wellheads looking north



20) Unmarked anchor on southwest corner of entrance

Inspection Photos
Location ID: 418750



21) Unmarked anchor on northwest corner of location