

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2017

Submitted Date:

08/01/2017

Document Number:

689300021**FIELD INSPECTION FORM**
 Loc ID 319475 Inspector Name: O'Donnell, Shaun On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1801 BROADWAY #500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
,		cogccinspections@gwogco.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243536	WELL	PR	12/08/2003	GW	123-11328	SIMPSON 1	SI
435698	TANK BATTERY	AC	04/14/2009		-	SIMPSON-66N67W 15NENE	AO

General Comment:

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead does not have a sign present		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/01/2017
Type	TANK LABELS/PLACARDS		
Comment:	Crude oil tank does not have contents or capacity posted, water vault does not have contents, capacity, or NFPA 704. See attached photos		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/01/2017

Emergency Contact Number:

Comment:	Adequate at battery, nothing posted at wellhead.	Date:	09/01/2017
Corrective Action:	Install sign to comply with Rule 210.b.		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.491340,-104.870320
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment: Animal burrows in the north and east of berms. See attached photos					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).					Date: 09/01/2017

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV CONCRETE		,	

Comment: Shares berm with crude oil tank					
Corrective Action:					Date:

Paint

Condition		
-----------	--	--

Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 243536 Type: WELL API Number: 123-11328 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI. Production records are showing no production since January 2015.Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 08/11/2017**BradenHead**Comment: Bradenhead plumbed to surfaceCorrective Action: Date: Facility ID: 435698 Type: TANK API Number: - Status: AC Insp. Status: AO**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300022	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213861