

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Battery signage from 6/20/2017 inspection, **Corrective action: No emergency contact info.**



Battery signage, **Corrective action: No update on emergency contact info.**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Inside oil/water tank berm, from 6/20/2017 inspection,
Corrective action: Stained soil.



Inside oil/water tank berm, **Corrective action: Stained soil not remediated.**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Separator, from 6/20/2017 inspection, **Corrective action: stained soil.**



Separator fire tube, **Corrective action: stained soil not remediated.**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Separator cabinet from 6/20/2017 inspection, **Corrective action: stained soil, leaking dump line.**



Separator cabinet, **Corrective action: Stained soil, leaking dump line.**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Wellhead from 6/20/2017 inspection, **Corrective action:**
Stained soil.



Weelhead, **Corrective action: Stained soil**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Wellhead signage from 6/20/2017 inspection, **Corrective action: No emergency contact info.**



Wellhead, pumping unit, and prime mover, **Corrective action, no signage, overgrown weeds.**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Pumping unit from 6/20/2017 inspection, **Corrective action: fittings and container full of paraffin.**

Pumping unit, **Corrective action: Container full of paraffin and fittings not remediated.**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Pumping unit from 6/20/2017 inspection, **Corrective action:**
Stained soil around engine mounts and frame.

Pumping unit, **Corrective action:** **Stained soil around prime mover and pumping unit frame not remediated.**

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Separator Cabinet: **Corrective action: Visible leak on dump valve**



Separator cabinet, audible leak on scrubber pot, note pressure gauge.

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Unidentified risers at separator (2)
39.984927, -104.855866



Unidentified riser at battery entrance (1)
39.985259, -104.856076

Inspection Photos
Location Name: Lambert 2
API: 05-001-08491



Water tank, **Corrective action: netting on open top ineffective.**



Wellhead, pumping unit, and prime mover.