

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2017

Submitted Date:

08/01/2017

Document Number:

687400121

FIELD INSPECTION FORM

Loc ID 320217 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 90615
Name of Operator: TUDEX PETROLEUM INC
Address: 1252 CAMERON RD
City: SEQUIM State: WA Zip: 98382

Findings:

- 18 Number of Comments
- 10 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
		dnr_enforcement@state.co.us	
CONN, LIONEL	403-870-5141	lconn@live.ca	inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203084	WELL	PR	12/01/2014	OW	001-08491	LAMBERT 2	PR

General Comment:

[Within 1000' NTO buffer](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	No emergency contact info at wellhead signage		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/30/2017
Type	BATTERY		
Comment:	Signage at battery has no emergency contact info.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/30/2017
Emergency Contact Number:			
Comment:	No emergency contact info on any signage		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/30/2017
Good Housekeeping:			
Type	WEEDS		
Comment:	Severely overgrown weeds at wellhead, see photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/10/2017
Type	UNUSED EQUIPMENT		
Comment:	Multile joints of 2"x30' tubing around wellhead.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	
Type	OTHER		
Comment:	Stained soil at wellhead, pumping unit frame around prime mover, under separator fire tube, inside separator cabinet, and behind production tank. See photos.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.	Date:	08/30/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Rod iron		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Battery, separator, and meter run are fenced with 4 strand barbed wire and double green gates.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas fired engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Conventional		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	Open Top		,	
Comment:	Fiberglass open top. Netting has fallen and is ineffective. See Photo.					
Corrective Action:	Install or repair wildlife protection equipment				Date:	08/10/2017

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:	Shares berm with production tank.			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:	Tank paint is out of compliance per rule 804					
Corrective Action:	Repair and paint tanks per Rule 804.				Date:	11/01/2017

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:	Weeds growing on berms. See Photos.				
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			Date:	08/10/2017

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203084 Type: WELL API Number: 001-08491 Status: PR Insp. Status: PR

Producing Well

Comment: [No production records since 12/2016.](#)

Corrective Action: [Submit required Form 7\(s\) to COGCC](#)

Date: 08/30/2017

COGCC Comments

Comment	User	Date
Location is in disrepair and appears to have not been maintained for several months. See attached PDF for details.	kraicha	08/01/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400122	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213981