

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2017

Submitted Date:

07/26/2017

Document Number:

682600339**FIELD INSPECTION FORM**
 Loc ID 324493 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757 #110City: HOUSTON State: TX Zip: 77227-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Eric Maestas		eric_maestas@oxy.com	
Axelson, John		john.axelson@state.co.us	
Kelley_Montgomery		Kelley_Montgomery@oxy.com	
Charles Terry		Charles_terry@oxy.com	
Shelby Schoepf		Shelby_Schoepf@oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150117	UIC DISPOSAL	AC	04/05/1982		-	GARCIA 1 (EPA)	EI
211777	WELL	IJ	06/15/2015	DSPW	055-06012	GARCIA (EPA) 1-WD	EI

**General Comment:**

This is an environmental inspection in response to reclamation inspection 673503751 that identified an large area of stained soil on the well pad. Any corrective actions from previous inspections that have not been addressed are still applicable.

Visual inspection and calculations based on aerial photography indicate that the spill is less than 5 barrels and contained entirely within secondary containment. The spill is not reportable under Rule 906. The operator was informed that cleanup of spill is still required and affected soil must meet Table 910-1 limits for soils.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>150117</u>	Type:	<u>UIC</u>	API Number: <u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>	
Facility ID:	<u>211777</u>	Type:	<u>WELL</u>	API Number:	<u>055-06012</u>	Status:	<u>IJ</u>	Insp. Status:	<u>EI</u>

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 4.5

Comment: Stained soil in containment northwest of produced water tank (see attached photos).

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 08/25/2017

Reportable: NO

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: 60

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401354726	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4208408">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4208408</a>
682600340	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4208373">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4208373</a>