

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Wellhead signage from 6/20/2017 inspection, no emergency contact info.



Wellhead signage, **Corrective action: emergency contact info not updated.**

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Tank battery signage from 6/20/2017. No emergency contact info.



Tank battery, **Corrective action: No emergency contact info updated, weeds, tank paint.**

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Tank battery signage from 6/20/2017. **No emergency contact info.**



Tank battery, **Corrective action: No emergency contact info updated, weeds, tank paint.**

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Outside of wellhead, Corrective action: Stained soil, weeds, and trash



Inside of separator housing, Corrective action: trash and stained soil around electric pump

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Inside of separator housing, Corrective Action: Stained soil inside of separator cabinet



Inside of separator housing, Corrective action: Stained soil at separator. Note Unidentified riser.

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Inside of separator housing, **Corrective Action: Trash and unused equipment storage.**



Inside of separator housing, **Corrective Action: Trash and unused equipment storage.**

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Inside of separator housing, Corrective Action: stained soil,
Note: Unidentified risers.



West of separator housing, Corrective Action: Trash and
weeds.

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Tank battery, Corrective Action: Berm maintenance and weeds.



Inside of oil/water tank berm, Corrective Action: stained soil and weeds.

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Inside of oil/water tank berm **Note: Unidentified riser (1)**
39.983695, -104-856856



Inside of oil/water tank berm **Note: Unidentified riser (1)**
39.983798, -104.865842

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Inside of oil/water tank berm **Note: Unidentified riser (1)**
39.983847, -104.865886



Inside of oil/water tank berm **Note: Unidentified riser (1)**
39.872831, -104.865848

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Inside of oil/water tank berm **Note: Unidentified riser (1)**
39.983829, -104.865873



Inside of oil/water tank berm **Note: Unidentified riser (1)**
39.983812, -104.865886

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



Inside of oil/water tank berm, riser detail



West of separator housing unit, Note: Unidentified riser (1)
39.983403, -104.865932

Inspection Photos
Location Name: Hi-Land 10B
API: 05-001-08767



**Pumping unit long run drum, 6/20/2017 inspection photo,
Corrective action, stained soil.**



**Pumping unit, Corrective action: stained soil not
remediated.**