

Inspection Photos
Location Name: Croff 12-5
API: 05-001-08162



Signage from 6/20/2017 inspection, No emergency contact info, unused scrubber.



Wellhead, **Corrective action: Emergency contact info not updated, scrubber not removed.**

Inspection Photos
Location Name: Croff 12-5
API: 05-001-08162



Stained soil at wellhead from 6/20/2017 inspection



Wellhead, **Corrective ation: stained soil not remediated.**