

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/26/2017

Submitted Date:

08/02/2017

Document Number:

687400124**FIELD INSPECTION FORM**

Loc ID 335737 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: 1252 CAMERON RDCity: SEQUIM State: WA Zip: 98382**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**22 Number of Comments12 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
		dnr_cogccenforcement@state.co.us	
CONN, LIONEL	403-870-5141	lconn@live.ca	<a href="#">inspections</a>
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203258	WELL	PR	08/01/2014	OW	001-08767	HI-LAND 10-B	PR
203259	WELL	PR	05/01/2015	OW	001-08768	HI-LAND 10-G	PR

**General Comment:**Within 1000' NTO buffer.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signage has no emergency contact info		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/31/2017
Type	BATTERY		
Comment:	Signage has no emergency contact info.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/31/2017

Emergency Contact Number:			
Comment:	No signs have have emergency contact info.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	08/31/2017

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Trash barrel at wellhead around fencing. See Photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	
Type	STORAGE OF SUPL		
Comment:	Operational parts and supplies are stored in separator housing. See photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	09/02/2017
Type	WEEDS		
Comment:	Weeds overgrown throughout location, around wellhead, pumping unit, separator housing, and in tank berms.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/11/2017
Type	TRASH		
Comment:	Trash inside of separator housing unit. See Photos.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soil around fencing at pumping unit, inside separator housing, around pumping unit long run drum, and on production tank rear drain valve. See photos.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.	Date:	08/31/2017

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		

Comment: <a href="#">Security chainlink around wellheads.</a>					
Corrective Action:				Date:	

  

<b>Equipment:</b>			corrective date		
Type: Prime Mover	# 1				
Comment: <a href="#">Gas fired engine</a>					
Corrective Action:		Date:			
Type: Other	# 1				
Comment: <a href="#">Fuel gas (propane) tank west of separator housing</a>					
Corrective Action:		Date:			
Type: Other	# 1				
Comment: <a href="#">240V tank bottom pump, has staining on pump, soil, housing, and associated piping. See photo</a>					
Corrective Action: <a href="#">Comply with Rule 603.f using the Rule 603.f guidance document for further details.</a>		Date: <a href="#">08/31/2017</a>			
Type: Pump Jack	# 1				
Comment: <a href="#">Conventional</a>					
Corrective Action:		Date:			
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:		Date:			
Type: Other	# 1				
Comment: <a href="#">Scrubber outside of separator housing to the west.</a>					
Corrective Action:		Date:			
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:		Date:			

  

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

  

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

  

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: <a href="#">Shares berms with production tank, see related correctiv actions and comments.</a>				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	Tank paint is out of compliance per COGCC rule 804, see photo				
Corrective Action:	Repair and paint tanks per Rule 804.				Date: 11/02/2017
<b>Paint</b>					
Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Berms walls are in disrepair on north end of production and water tank. Weeds are growing on berms. See photos.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 08/31/2017
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 203258 Type: WELL API Number: 001-08767 Status: PR Insp. Status: PR**Producing Well**Comment: Production records are not up to date, last submitted 1/2016.Corrective Action: Submit required Form 7(s) to COGCCDate: 08/31/2017Facility ID: 203259 Type: WELL API Number: 001-08768 Status: PR Insp. Status: PR**Producing Well**Comment: Production records are not up to date, last reported 1/2016.Corrective Action: Submit required Form 7(s) to COGCCDate: 08/31/2017**COGCC Comments**

Comment	User	Date
Well flows to commingled battery with Hi-Land 10G (05-001-08768). All surface equipment and related corrective actions will be identified and called out on this inspections form.	kraicha	08/02/2017
Location, and equipment appears to have not been operated or maintained in some time.		
Location has several unidentified risers inside of separator housing and withing tank berms. See attached photos for descriptions and GPS locations.		

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400126	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214802">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214802</a>