



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3: View of the northwestern portion of the project area from the northwestern corner facing eastward.



Photo 4: View of wattle on the northeastern edge full of sediment that needs maintenance.



Photo 5: View of wattles along the eastern edge of the well pad where stormwater is flowing beneath the wattle and needs maintenance.



Photo 6: View of sediment trap east of the well pad entrance.