

Interim Reclamation Inspection

August 1, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 438023

Weld County, CO

NWSE Section 36 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: DEJANE STATE TANK BATTERY /2N-36HZ

Location ID: 438023



Google Earth aerial imagery taken September 7, 2016 illustrating the flowline area and well pad that are the subject areas for this follow up interim reclamation inspection (outlined in the green dashed line).

Inspection Photos

Location Name: DEJANE STATE TANK BATTERY /2N-36HZ

Location ID: 438023



Photo 1. Photo taken from the northwest, east flowline area, facing East. Desirable plant species establishment is evident throughout most of the flowline area.



Photo 2. Photo taken from the northwest, east flowline area, facing South. Desirable plant species establishment is evident throughout most of the flowline area. The western portion of the east flowline area has vegetative gaps and is not uniform. Longspine sandbur (*Cenchrus longispinus*) was observed along portions of this area.

Inspection Photos

Location Name: DEJANE STATE TANK BATTERY /2N-36HZ

Location ID: 438023



Photo 3. Photo taken from the central, east flowline area, facing East. Desirable plant species establishment is evident throughout this area.



Photo 4. Photo taken from the south central, east flowline area, facing East. This area has vegetative gaps and is not uniform. Longspine sandbur (*Cenchrus longispinus*) was observed along portions of this area.

Inspection Photos
Location Name: DEJANE STATE TANK BATTERY /2N-36HZ
Location ID: 438023



Photo 5. Photo taken from the east, west flowline area, facing North. This area has vegetative gaps and is not uniform. Longspine sandbur (*Cenchrus longispinus*) was observed along portions of this area.



Photo 6. Photo taken from the central, west flowline area, facing West. Desirable plant species establishment is evident throughout this area.

Inspection Photos

Location Name: DEJANE STATE TANK BATTERY /2N-36HZ

Location ID: 438023



Photo 7. Photo taken from the north central, west flowline area, facing East. Desirable plant species establishment is evident throughout most of this area.