

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2017

Submitted Date:

08/03/2017

Document Number:

688000041**FIELD INSPECTION FORM**Loc ID 316940 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler12@gmail.com	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107604	PIT	AC			-	BEN 1	EI
107605	PIT	AC			-	BEN 1	EI
107606	PIT	AC			-	BEN 1	EI

General Comment:[Environmental inspection related to Rem #9398.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Oily soil near wellhead.

Corrective Action: Clean up oily soil and properly dispose.

Date: 08/31/2017

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities								
Facility ID:	107604	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	107605	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	107606	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: NOPit ID: 107604Lat: 39.763475Long: -103.351791Reference Point: SEOther: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Oil skim pit has been bypassed using an oil skim tank, still contains oil and water.Corrective Action: Remove contents of the oil skim pit to facilitate drying of pit soils.Date: 08/31/2017c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000042	Location Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4216680