

Location

Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stickers and stencils on tanks		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Wire fence around unit and wellhead		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Wire fence around tank battery		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 213009 Type: WELL API Number: 061-06370 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: MIRU ECWS. RIH W/BRIDGE PLUG TO 4920'. LOAD CSG W/1BBL. PRESSURED UP TO 400 PSI. 5 MIN 400#. 10 MIN 400#. 15 MIN 400#. LOSS OF 0 PSI

Corrective Action: Date: _____

Workover

Comment: ECWS RIG #37 on location to set bridge plug and swab well

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679902827	Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217657