

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2017

Submitted Date:

07/31/2017

Document Number:

690100027

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
321345 _____ Maclaren, Joe _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10575
Name of Operator: 8 NORTH LLC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Carlisle, Josh		jcarlisle@extractionog.com	
,		COGCCInspections@extractionog.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206752	WELL	SI	05/01/2017	GW	013-06247	DONLEY 2-36	EG

General Comment:

Engineering Integrity Inspection performed on July 25th, 2017 in response to initial form 19 spill report Doc #401347902 received by COGCC on 07/19/2017 that outlines: While completing required tests of flowlines at the location, the water dump line failed a pressure test. During the subsequent investigation, impacted soil was identified along the flowline corridor between the separator and production tank. Details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

Inspected Facilities

Facility ID: 206752 Type: WELL API Number: 013-06247 Status: SI Insp. Status: EG

Flowline

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material:
 Variance: Age: Contents: Produced Water

Integrity Summary

Failures: Spills: Yes Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: There were no Extraction or contract personnel on site at the time of this field inspection. The impacted surface has been grubbed/ cleaned up. Dump flowline repairs appear to be scheduled for completion. Note: Document and retain records of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of all repairs completed (on supplemental form 19); perform flowline pressure testing to verify integrity of repairs/ replacements completed (retain chart & data) prior to returning dump lines to service.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401358844	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4211760
690100036	Signage at Tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4211755
690100037	Recent cleanup/ dirt work on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4211756