

- Davis 2-5 05-067-08150



Photo 1: Wellhead sign.

- Davis 2-5 05-067-08150



Photo 2: Rilling on cut slope.

- Davis 2-5 05-067-08150



Photo 3: 1" poly line at wellhead.

- Davis 2-5 05-067-08150



Photo 4: 1" poly line at separator.

- Davis 2-5 05-067-08150



Photo 5: Erosion developing on fill slope.

- Davis 2-5 05-067-08150



Photo 6: Erosion developing on fill slope.