

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2017

Submitted Date:

08/07/2017

Document Number:

679100118**FIELD INSPECTION FORM**Loc ID 320858 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Naomi Azulai		naomi.azulai@bp.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

General Comment:

Date of Inspection: 4-21-17

Type of Inspection: Flowline Hydrostatic Testing, Interim Reclamation, Containment, Stormwater

Location Name: Carmelita Gallegos A 1 Pad; Carmelita Gallegos A 3 well

Location ID #: 320858

Form 2A# 401156218

API #: 05-007-06325

Construction stormwater BMPs for this well pad expansion and the original well pad (perimeter berm, diversion trenches, silt fences, straw wattles, rock check dams, and other spill stormwater control equipment) and access road (borrow ditch with rock check dams for sediment control) are mostly in-place and these stormwater controls indicate no offsite migration of fluids or sediment; cut and fill slopes of the original well pad have been partially to mostly re-vegetated; observed hydrostatic static testing of onsite water and gas flowlines from the wellhead to the separator and take away pipelines; all flowlines and pipelines were tested a minimum of 2 hours at pressures greater than estimated operating pressures (>950 psi); all flowlines and pipelines passed.